



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 001

Date: June 7, 2010

Direction: Northeast

Photographer: Michael Browning

Subject: Pontoon bridge leading from the south side of the Kalamazoo River to Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 002

Date: June 7, 2010

Direction: Northeast

Photographer: Michael Browning

Subject: Staging Area 1 during construction.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 003

Date: June 7, 2010

Direction: Northwest

Photographer: Michael Browning

Subject: Command Post area located immediately west of Staging Area 1.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 004

Date: June 8, 2010

Direction: Southeast

Photographer: Michael Browning

Subject: Terra excavator operator loading cut trees onto an offroad dumptruck.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 005

Date: June 10, 2010

Direction: East

Photographer: Michael Browning

Subject: Terra excavator operator using a pair of shears to break and bundle the trees that are cut down on the small island near Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 006

Date: June 16, 2010

Direction: Southeast

Photographer: Michael Browning

Subject: Arcadis workers installing turbidity curtains upstream of the Island 2 pontoon barge.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 007

Date: June 16, 2010

Direction: Southeast

Photographer: Michael Browning

Subject: A load of impacted sediment being unloaded onto the pad at Staging Area 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 008

Date: June 17, 2010

Direction: Northwest

Photographer: Michael Browning

Subject: Sediment excavation on the northern side of Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 009
Direction: North
Subject: Silt fence installation near Staging Area 2.

Date: June 24, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 010
Direction: Northwest
Subject: Terra personnel lining the bed of a dumptruck trailer with plastic prior to the dumptruck being loaded with sediment at Staging Area 2.

Date: June 24, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 011

Date: June 24, 2010

Direction: East

Photographer: Michael Browning

Subject: Terra crew performing restoration activities on the northern side of Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 012

Date: June 29, 2010

Direction: East

Photographer: Jay Rauh

Subject: Excavation activities on Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 013

Date: June 30, 2010

Direction: West

Photographer: Jay Rauh

Subject: Truck hauling material over the temporary bridge.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 014

Date: July 7, 2010

Direction: North

Photographer: Michael Browning

Subject: Ongoing restoration activities along the northern side of Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 015

Date: July 7, 2010

Direction: Northeast

Photographer: Michael Browning

Subject: Terra water truck deconning a Fulton trailer prior to the Fulton truck at Staging Area 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 016

Date: July 8, 2010

Direction: Down

Photographer: Michael Browning

Subject: Arcadis sampler collecting a surface water sample from the Kalamazoo River by releasing the contents of a bomb sampler into a 1-liter amber bottle.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 017

Direction: North

Subject: JFNew personnel installing biologs along the northern side of Island 2.

Date: July 9, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 018

Direction: South

Subject: Terra operator loading an offroad dumptruck with sand that will be used in the restoration of the grids near the southeastern corner of Island 2.

Date: July 9, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 019

Direction: Northeast

Subject: Excavation of sediment from Area 3B.

Date: July 12, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 020

Direction: Northeast

Subject: Turbidity curtain removal and biolog placement at the southeastern corner of Island 2.

Date: July 12, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 021

Date: July 12, 2010

Direction: Northeast

Photographer: Michael Browning

Subject: Removal of the turbidity curtain from the area near the southeastern corner of Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 022

Date: July 14, 2010

Direction: West

Photographer: Michael Browning

Subject: Newly restored southeastern corner of Island 2.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 023

Date: July 15, 2010

Direction: Northwest

Photographer: Michael Browning

Subject: JFNew installing biologs along the northwestern corner of Island 2, as well as Terra removing turbidity curtain poles in the same area.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 024

Date: July 15, 2010

Direction: Northwest

Photographer: Michael Browning

Subject: Arcadis collecting a water sample from the Kalamazoo River.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 025

Date: July 20, 2010

Direction: East

Photographer: Michael Browning

Subject: Terra operator removing a crane mat that had originally been located on top of the pontoon bridge.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 026

Date: July 21, 2010

Direction: Southeast

Photographer: Michael Browning

Subject: Terra worker powerwashing the exterior of a pontoon barge section.



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 027
Direction: Southeast
Subject: Excavation of Grids 1 and 2 in the oxbow area.

Date: August 5, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 028
Direction: West
Subject: Collection of sample material from Grids 1 and 2 of the oxbow area.

Date: August 6, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 029

Direction: Southeast

Subject: Excavation in the upland section of Area 5B.

Date: August 6, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 030

Direction: Southeast

Subject: JFNew workers putting biologs in place in Area 4B.

Date: August 10, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 031

Direction: East

Subject: Restoration activities in Area 3B.

Date: August 10, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 032

Direction: Northwest

Subject: Automatic tirewashing deconning the tires of a dumptruck that had just been loaded with sediment.

Date: August 17, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 033
Direction: North
Subject: Sediment pugging operations at Staging Area 1.

Date: August 18, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action
Photograph No.: 034
Direction: Southwest
Subject: Excavation activities in the oxbow.

Date: August 21, 2010
Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 035

Direction: Southeast

Subject: Restoration activities in Area 6.

Date: September 9, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 036

Direction: South

Subject: Terra worker using a powerwasher to decontaminate a section of turbidity curtain.

Date: September 20, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 037

Direction: Northwest

Subject: Arcadis representatives collecting sample material from Grid 12 of Area 5B.

Date: September 23, 2010

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 038

Direction: East

Subject: Restoration activities in Area 5B.

Date: September 27, 2010

Photographer: Michael Browning